


Maule Aircraft Corporation

6780 BROOKLYN ROAD

JACKSON, MICHIGAN - 49201

PHONE KE 6-8642
AREA CODE 517

JANUARY 10, 1964

Service Letter No. 3
Model Effected M-4
Serial Number Effected 3 thru 46

Dear Customer:

There has been some binding and brake locking on the type of brake assembly used on our aircraft.

We would like you to have your aircraft inspected so as to preclude any chance of an accident.

The following areas should be checked:

1. Brake shoe movement. Check for burrs on inside surfaces of brake shoe pivot bolt shackle plates.
2. Brake cylinder piston binding.
3. Adjustment of axle nut (no end play in bearing or binding).

Any improper operation should be immediately corrected. Should any improper operation be noted, it would be appreciated if you would notify the factory to aid us in our efforts to eliminate this condition.

Very truly yours,

MAULE AIRCRAFT CORPORATION



Daniel L. Yother
Project Engineer

DLY/jh

MAULE AEROSPACE TECHNOLOGY, INC.

SERVICE LETTER #3 - COMPLIANCE RECORD

Airplane Serial Number _____

Airplane Registration Number _____

The following action was taken with respect to this service letter:

Service letter #3 completed

Certified by _____

(Signature)

(Printed Name)

Title _____

(Owner, A&P), IA, etc.)

In an effort to keep our mailing list current for sending Service Letters, Service Bulletins, etc., please fill in the following:

Owner's name _____

Owner's address _____

Mail this Compliance Record to: Maule Aerospace Technology, Inc.
Engineering Records
2099 GA Hwy. 133 S.
Moultrie, GA 31788