



28 Sept. 1978

Page 1 of 2

## SERVICE LETTER # 40

Subject: Flap Placard

Airplanes Affected: All M-5 Models, 5000C, 6000C and 7000C series serial numbers through 5057C, 6204C and 7219C.

Compliance: Within 50 Flight Hours

Status: Necessary to comply with CAR 3.

Authority: This Service Letter is FAA approved


Background: A placard is required on the flap handle, and it is possible that this placard was left off of some of these airplanes.

Material Required: One flap handle placard, enclosed with this service letter.

Corrective Action: If your airplane already has this placard, on the flap handle, complete and return the attached form and log compliance in your aircraft log book.

If it does not have this placard, make sure the upper surface of the flap handle, just aft of the grip, is clean. Peel the backing from the placard and attach the placard to the flap handle as shown in the sketch.

Complete the attached Service Letter Compliance Record and return to Maule Aircraft Corporation. Log compliance in your aircraft log book.





MAULE AIRCRAFT CORPORATION

SERVICE LETTER # 40 COMPLIANCE RECORD

Airplane Serial Number \_\_\_\_\_

Aircraft Registration Number \_\_\_\_\_

The following action was taken with respect to this service letter: (Check One)

This aircraft was already equipped with the subject placard.

The Placard has been attached to the flap handle as shown in this service letter.

I no longer own this airplane. It was sold to:

NAME \_\_\_\_\_

ADDRESS \_\_\_\_\_

CITY, STATE, ZIP \_\_\_\_\_

Certified by \_\_\_\_\_  
SIGNATURE

PRINTED NAME \_\_\_\_\_

Title \_\_\_\_\_  
OWNER, A&P, IA, ETC.

Return this Compliance Record to: Maule Air, Inc.  
2099 GA Hwy. 133 S.  
Moultrie, GA 31788  
ATTN: Engineering Records